Sky Valley - Indoor Air Quality Assessment Sampling Plan (FINAL) February 9, 2016

The following is a draft sampling plan for testing and analysis at the above site. The list below shows the constituents then the location(s).

Campus Wide

- 1. Damaged suspect lead-containing paints
- 2. Damaged suspect exterior PCB-containing paints, caulking, putties and sealants
- 3. All interior suspect PCB-containing materials
- 4. PCB air and surface every classroom and common area, and representative offices and storage/prep areas
- 5. Water quality testing lead and copper

Administration Bldg.

- 1. CO2, CO, Relative humidity, Temperature Reception, Staff
- 2. Particulate air (fungal and non-fungal airborne particulate) Reception, Staff
- 3. Particulate surface (accumulated surface dust fungal and non-fungal particulate) Reception, Staff
- 4. Radon Reception, Staff
- 5. Formaldehyde Reception, Staff
- 6. TVOC's (total volatile organic compounds) Reception, Staff
- 7. Asbestos in accumulated surface dust Reception and Staff
- 8. Asbestos air Reception and Staff
- 9. Dust mite allergen Reception, Staff

Annex Bldg.

- 1. CO2, CO, Relative humidity, Temperature Rm B, Rm C, Rm D
- 2. Part. air Rm B, Rm C, Rm D
- 3. Part. surface Rm B, Rm C, Rm D
- 4. Radon Rm B, Rm C, Rm D
- 5. Formaldehyde Rm B, Rm C, Rm D
- 6. TVOCs Rm A, Rm B, Rm C, and Custodial closets
- 7. Asbestos air Rm B, Rm C, Rm D
- 8. Asbestos in accumulated surface dust Rm B, Rm C, Rm D
- 9. Dust mite allergen Rm B, Rm C, Rm D

Gym/Music Bldg.

- 1. CO2, CO, Relative humidity, Temperature Music, gathering, east gym (small gym), girls locker, CTE
- 2. Part. air Music, Gathering, East Gym (small gym), Girls Locker, CTE
- 3. Part. surface Gathering, Small Gym, CTE
- 4. Formaldehyde gyms with floor and wall pads
- 5. TVOC's Custodial closets
- 6. Asbestos air Café, Gathering, one restroom
- 7. Asbestos in accumulated surface dust Music, Gathering, East Gym (small gym), Girls Locker, CTE
- 8. Radon Music, Small Gym, Gathering
- 9. Dust mite allergen Music, Gathering, CTE

ED_001594_00089258 EPA_005619

SVEC
Draft IAQ Sampling Plan
February 1, 2016
Page 2 of 3

Main Bldg. - Library

- 1. CO2, CO, Relative humidity, Temperature one location
- 2. Part. air one location
- 3. Part. surface one location
- 4. Formaldehyde one location
- 5. TVOCs Custodial closet
- 6. Dust mite allergen one location
- 7. Asbestos air one location
- 8. Asbestos in accumulated surface dust one location
- 9. Radon one location

Main Bldg. - East Pod

- 1. CO2, CO, Relative humidity, Temperature Rm 9, 11, 13, Center Pod
- 2. Part. air Rm 9, 11, 13, Center Pod
- 3. Part. Surface Rm 9, 11, 13, Center Pod
- 4. Formaldehyde Rm 9, 11, 13, Center Pod
- 5. TVOCs Rm 9, 11, 13, Center Pod
- 6. Dust mite allergen Rm 9, 11, 13, Center Pod
- 7. Asbestos and silica air Rm 9, 13, Center Pod
- 8. Asbestos in accumulated surface dust Rm 9, 13, Center Pod
- 9. Radon Rm 13, Center Pod
- 10. Calcium carbonate/crystalline silica air (concrete grinding areas)- Rm 8, 11, 12, Center Pod
- 11. Pesticides and PCB Analysis Carpet pieces provided to PBS from Rooms 8, 12, Center Pod
- 12. Fungi, asbestos, dust mite, and non-fungal particulates Leahy air filter Room 11

Main Bldg. - North Pod

- 1. CO2, CO, Relative humidity, Temperature Rm 14, 18, 20, Center Pod
- 2. Part. Air Rm 14, 18, 20, Center Pod
- 3. Part. Surface Rm 14, 18, 20, Center Pod
- 4. Formaldehyde rep Rm 14, 18, 20, Center Pod
- 5. TVOCs Rm 14, 18, 20, Center Pod
- 6. Dust mite allergen rep Rm 14, 18, 20, Center Pod
- 7. Asbestos and silica air Rm 14, 20, Center Pod
- 8. Asbestos in accumulated surface dust Rm 14, 20, Center Pod
- 9. Radon Rm 14, Center Pod

ED_001594_00089258 EPA_005620

SVEC
Draft IAQ Sampling Plan
February 1, 2016
Page **3** of **3**

Main Bldg. - South Pod

- 1. CO2, CO, Relative humidity, Temperature Rm 2, 4, 5, 6, 7, Center Pod
- 2. Part. air Rm 2, 4, 5, 6, 7, Center Pod
- 3. Part. surface Rm 2, 4, 5, 6, 7, Center Pod
- 4. Formaldehyde Rm 2, 4, 5, 6, 7, Center Pod
- 5. TVOCs Rm 2, 4, 5, 6, 7, Center Pod
- 6. Dust mite allergen Rm 2, 4, 5, 6, 7, Center Pod
- 7. Asbestos and silica air Rm 2, 4, 6, 7, Center Pod
- 8. Asbestos in accumulated surface dust Rm 2, 7, Center Pod
- 9. Radon Rm 5, Center Pod
- 10. Soil outside rooms 4, 5, 6, & 7 (representative locations)

Main Bldg. - Attic Spaces

- 1. Part. air North, South, and East Pods
- 2. Part. surface North, South, and East Pods
- 3. TVOCs North, South, and East Pods
- 4. Dust mite allergen North, South, and East Pods
- 5. Asbestos air North, South, and East Pods
- 6. Asbestos in accumulated surface dust North, South, and East Pods

Technology Bldg.

- 1. CO2, CO, Relative humidity, Temperature Art, Wood shop
- 2. Part. air Art, Wood shop
- 3. Formaldehyde Art, Wood shop
- 4. TVOCs Art, Wood shop, Custodial closet
- 5. Radon Art, Wood shop
- 6. Silica air Art
- 7. Asbestos air Art, Wood shop
- 8. Asbestos in accumulated surface dust Wood shop, Rm 23

NOTE: PBS Environmental will endeavor to follow this outline to the extent possible. Please understand that this plan is subject to the industrial hygienist discretion at the time of sampling. Certain activities or conditions may preclude specific areas from sampling, and the location or number of samples may need to be adjusted.